

Recall Information

Slant/Fin Victory Boiler

Recall Date: October 18, 2018

Product Description	UPC	Model #	Internet #
Slant/Fin Victory Natural Gas Direct Vent Hot Water Boiler with 60,000 Input BTU and 45,000 Output BTU	042541064813	VSPH-60	202783249
Slant/Fin Victory Natural Gas Direct Vent Hot Water Boiler with 90,000 Input BTU and 68,000 Output BTU	042541064905	VSPH-90	202783250
Slant/Fin Victory Natural Gas Direct Vent Hot Water Boiler with 120,000 Input BTU and 90,000 Output BTU	042541085689	VSPH-120	205880860
Slant/Fin Victory Natural Gas Direct Vent Hot Water Boiler with 150,000 Input BTU and 111,000 Output BTU	042541065179	VSPH-150	202783247



Name of Product: Slant/Fin Victory Natural Gas Direct Vent Hot Water Boiler

Hazard: A malfunction in the recalled controller can cause the boiler to overheat, posing a fire hazard.

Remedy: Repair.

Consumers with Slant/Fin model VSPH boilers should immediately contact a contractor to schedule a free repair. For assistance in locating a contractor, go to <http://www.slantfin.com/locator/>.

Consumer Contact: Slant Fin at 800-873-4346 from 9 a.m. to 5 p.m. ET, Monday through Friday or Hydrolevel at 800-654-0768 from 8 a.m. to 5 p.m. ET, Monday through Friday or online at www.hydrolevel.com and click Contact Us for more information.

Post until August 1, 2019